DDAS Accident Report

Accident details

Report date: 27/01/2008 Accident number: 522

Accident time: Not made available Accident Date: 01/09/2005

Where it occurred: Not made available Country: Lebanon

Primary cause: Unavoidable (?) Secondary cause: Management/control

inadequacy (?)

Class: Excavation accident Date of main report: Not made available

Map series:

ID original source: None Name of source: [Name removed]

Organisation: [Name removed]

Mine/device: No.4 Israel AP blast / Ground condition: not recorded

frag

Date record created: Date last modified: 27/01/2008

No of victims: 1 No of documents: 1

Map details

Longitude: Latitude:

Alt. coord. system: Not made available Coordinates fixed by:

Map east: Map north:

Map edition: Map sheet:

Map name:

Map scale:

Accident Notes

inadequate investigation (?)

Accident report

Details of this accident have been withheld by the demining NGO that employed the Victim. A spreadsheet including the Victim's name and very brief details of the accident was made available in 2007. Some details can be inferred from the information released. For example, the limited injury implies that the victim's PPE was being worn in the correct manner.

This entry will be expanded if access to the report of the investigation is made available in future.

The spreadsheet data is reproduced below, edited for anonymity.

"Date and country. [Name removed]: Traumatic amputation of left hand below elbow.

Mine accident - mine activated whilst deminer excavating site - Israeli No 4 mine"

Victim Report

Victim number: 688 Name: [Name removed]

Age: Gender: Male

Status: deminer Fit for work: not known

Compensation: Not made available Time to hospital: Not made available

Protection issued: Not recorded Protection used: Not made available

Summary of injuries:

AMPUTATION/LOSS: Arm Below elbow

COMMENT: No Medical report was made available.

Analysis

The primary cause of this accident is listed as "Unavoidable" because it is possible that the Victim was working properly in the way that he was trained, and that he was also using a long and blast resistant tool when the accident occurred.

The secondary cause is listed as a "Management control inadequacy" because the management of the demining group declined to make the accident details available. Although this is sometimes done to protect the Victims, in this case the Victim's name was among the limited detail made available. It is possible that the managers have chosen to avoid transparency because they are afraid that the circumstances of the accident would reflect badly on their organisation.